



SFM Fire Inspection Report

Inspection Information

Inspection Date: 11/24/2020
Inspection No: 002156

Inspection Type: Consultation - Follow-Up

Facility Information

SWWC Educational Learning Center-Windom
1454 6th Avenue Windom, MN 56101
Email:

***Property Use:** ED - Special education

Occupant Loads

No Occupant Loads Found

Primary Contact

Kratochvil, Jason (Site Administrator) Work Phone: 507-831-6935 ext. 1812 | Email: jason.kratochvil@swsc.org
Roessler, Tom (State Inspector) Email/Cell: thomas.roessler@state.mn.us (507) 602-0651

Violations

On the above date, an inspection was conducted for the purposes of fire and life safety. The following conditions were observed that do not meet the minimum requirements of the Minnesota State Fire Code. Failure to correct identified fire and life safety deficiencies in a timely manner is a criminal violation pursuant to Minn. Stat. § 299F.011, subd. 6. There is a variance procedure available. Please contact the inspector named for further assistance.

Code - Description

** MSFC 2020 - 1010.1.11 : Provide special detention arrangements in accordance with MSFC -OR- remove such unapproved locking arrangements from doors.
- Violation Location: Room 103B and 111B
- Comments: Install electrical interconnect between seclusion room lock and activation of fire alarm trouble signal in accordance with MSFC 1010.1.11.1. ORDER CORRECTED.

Violation Status

Violation Repaired

Inspection Notes

Notes: Requested documentation received showing the seclusion room lock is connected to trouble signal on panel. Seclusion room meets the requirements of the MSFC.

End of Report

Signature:

Date: 11/25/2020